

Other Creek Crossing Photos



Exposed, damaged Enterprise High Pressure Natural Gas Liquids (NGL) Pipeline in a Small Creek Near Camino De La Rosa Castilla.



A Second Exposed Enterprise High Pressure NGL Pipeline in a Creek.